






REVISIONS

ZONE	REV	DESCRIPTION	DATE	APPROVED
------	-----	-------------	------	----------

Ext Fin Can V2.1 Step 6

- 1) Using 3/8" end mill, cut fin can off of the chuck.
Cut line is at X=-.188" (Or, X=0 with tool offset).
- 2) Drill and tap fin tab holes.



SIZE A	FSCM NO.	DWG NO.	REV
SCALE	B. Feretich	SHEET	

